




- DE** Montageanleitung
FR Instructions de montage
EN assembly instructions
IT Istruzioni per Installazione
ES Instrucciones de montaje
NL Handleiding
DK Monteringsvejledning
PT Manual de Instalação
PL Instrukcja montażu
CS Montážní návod
SK Montážny návod
ZH 组装说明
RU Инструкция по монтажу
HU Szerelési útmutató
FI Asennusohje
SV Monteringsanvisning
LT Montavimo instrukcijos
HR Uputstva za instalaciju
TR Montaj kılavuzu
RO Instrucțiuni de montare
EL Οδηγία συναρμολόγησης
SL Navodila za montažo
ET Paigaldusjuhend
LV Montāžas instrukcija
SR Uputstvo za montažu
NO Montasjeveiledning
BG Инструкция за употреба
SQ Udhëzime rreth montimit
AR تعليمات التجميع




Crometta 1jet
6 l/min
26334400



Crometta Vario
6 l/min
26336400



Crometta 1jet
6 l/min
26334400



Crometta Vario
6 l/min
26336400








P max. 0,6 MPa 0,1 - 0,4 MPa
6 bar 1 - 4 bar




T max. 60 °C 40 - 50 °C







Crometta 1jet 26334400



- ① Rain
- ② IntenseRain

94246000





P-IX

DVGW

SVGW

ACS






WRAS

NF

KIWA

26334400

26336400



hansgrohe

Hansgrohe · Auestraße 5 · 9 · D-77761 Schiltach
Telefon +49 (0) 78 36/51-1282 · Telefax +49 (0) 7836/511440
E-Mail: info@hansgrohe.com · Internet: www.hansgrohe.com

12/2015
9.04746.01