




=Important measure

We have noticed that some of the adapters have to loose fit between the holder and wedge. If you hold the wedge the holder slides off downwards







The measurement must be equal on all sides

